



Follow-up Service Inspection Report MH49259424011194442

INSPECTION DETAILS			
Date:	2024-01-11	File Number.:	MH49259
Responsible Office:	Northbrook	Volume:	4
Inspection Center:	366	CCN:	FDNP
Product Type:	Water	UL Rep Name:	Alexey Manoylin
Deliverable Type:	Listed	UL Rep ID:	86523
Party Site Number:	3429185	Subscriber Factory No.:	
Manufacturer Name:	ASAF AVIZARIM LTD	Factory Rep Name:	Mr. Aviad Swissa
Manufacturer Address:	Asimov 7 Yeruham , Yeruham	Factory Rep Phone:	+972-50-2021129
		Factory Rep Email:	Aviadsu@asafitd.co.il
Applicant:	KRAUSZ INDUSTRIES LTD (571975) 1 HaRav Shalom Mantsura st. 4850001 (3rd Floor) Rosh HaAyin IL		
Nature of visit:	Initial Production Inspection	Sample Status:	Samples not required
UL Marks Used?	No	UL Marks Removed?	No
Variation Notice Issued?	No	Specific Environmental Conditions Required?	No

PRODUCT DOCUMENTS/PRODUCTION READY VISIT			
Model	Product	Section	Multiple Listed
Hymax 2	DRINKING WATER SYSTEM COMPONENTS	4	No

UL-OWNED EQUIPMENT CALIBRATION
No UL Owned IMTE used during inspection.

COMMENTS	
Additional Comments	As part of the initial product inspection under split inspection requirements, product found acceptable for extraction to the market from the Yeruham factory. Checked knowledge of UL Follow-up services rules. Explained FE and applicant's/ manufacturer's responsibilities. Fully reviewed all relevant documentation for the project and product. Production floor/ test corner/ warehouse observed. Future plans and current situation discussed. myUL portal is active for applicant and not yet for manufacturer, details explained
Comments After Submission:	

In addition to the requirements specified in the applicable UL Services agreement and Follow-Up Service Procedure, UL further defines responsibilities, duties and requirements for both manufacturers and UL representatives in the document titled "UL Mark Surveillance Requirements" that can be located at www.ul.com/fus, and in accordance with the applicable terms and conditions of the document at www.ul.com/responsibilities. Manufacturers without Internet access may obtain the current versions of these documents from their local UL



Follow-up Service Inspection Report MH49259424011194442

customer service representative or UL field representative. The Field Engineer is completing the inspections per Internal Procedure UL Mark Surveillance Program Policy Manual -ULID-004573.